

Homepage:

YOKOHAMA has decided to conduct a **voluntary replacement program** (recall) on its article "B5103 - 385/55R22.5 158L - 126S".

Under certain circumstances irregular production geometry may lead to a sidewall crack at the shoulder area. In rare cases this crack could progress and possibly causing air loss, increasing the risk of accident.

We therefore kindly ask you to immediately inspect your tyres if these are affected and in case of affected tyres contact your tyre dealer or contact us at Support Call Center (telephone number and e-mail address can be found below, in order to arrange for cost free replacement of your affected tyres).

+49 211 529420

service@yokohama.eu

The affected Tyres are described in more detail in the table below:

Tyre Model [Product Name]	Tyre Size	Article Number	Tyre Serial Begins with	Tyre Serial Ends with
126S	385/55R22.5 158L	B5103	FBVHYYY	0123 ~ 3925

How do I identify if my tyre is affected by this voluntary replacement program?

1. Read manufacturer name "YOKOHAMA"

2. Read product name "126S"

3. Read tyre size on the sidewall "385/55R22.5"; "158L"

4. Read tyre serial indication "FBVHYYY 0123 to 3925"

1. Manufacturer Name

2. Product Name

3. Tyre Size

4. Tyre Serial Indication

We regret to cause our customers an inconvenience, but safety and quality is of highest priority for us. We will further strengthen our efforts to prevent recurrence and strive to justify customer trust.